


Exploded views/tables

W2315



7000590

Ref. No.	Ordering No.	Qty	Description	Remark / Included in Service kit
1	-	1	Housing	
2	-	1	Bushing	Preassembled in Ref.No. 1
3	-	1	Seal	Preassembled with Ref.No. 4
4	-	1	Screw	Service kit 4081 2031 90
5	-	1	Valve Seat	Service kit 4081 2031 90
6	-	1	Throttle Valve	Service kit 4081 2031 90
7	-	1	Valve Spring	Service kit 4081 2031 90
8	-	1	Exhaust Deflector	Service kit 4081 2031 90
14	-	2	O-Ring	Service kit 4081 2029 90, Service kit 4081 2030 90
15	-	1	Trigger	Service kit 4081 2029 90
16	-	1	Ornamental Gasket	Service kit 4081 2033 90
17	-	1	O-Ring	Service kit 4081 2030 90
18	-	1	Reverse Switch	Service kit 4081 2037 90
19	-	1	Valve bushing	Preassembled with Ref.No. 20
20	-	1	Reverse Bushing	Service kit 4081 2037 90
21	-	1	Spring	Service kit 4081 2029 90
22	-	1	Steel Ball	Service kit 4081 2029 90
23	-	1	End Cap	Service kit 4081 2037 90